
REDCO APPLICATION AND TROUBLE SHOOTING GUIDE





REDCO UFO APPLICATIONS

MODEL	TYPE	PLL CHIP USED	DIGI-SCAN REQUIRED
PRESIDENT			
Adams Andrew J (old) Dwight D (old) Grant (old) Honest Abe John Q Madison Old Hickory Teddy R Washington Zachary T Washington (new) Zachary T Dwight D Grant McKinley Andrew J	S A A S A A S A A S A A S A A S A A	858 858 858 858 858 858 858 858 858	RDS-1, UFO RDS-6, UFP N/A N/A RDS-5, UFO RDS-6, UFO
Thomas J Veep Madison	A A S	2816 9109 8719	N/A N/A RDS-5
COBRA			KD2-2
21 GTL 21 XLR 25 GRL 29 GTL 29 XLR 32 XLR 77 XLR 78 XLR 87 GTL 89 GTL	A A A A	TC9106 858 TC9106 UPD2816 858 5080 858* 858* 2816 2816	N/A RDS-1*, UFO N/A N/A RDS-1*, UFO N/Z UFO UFO N/A N/A
132 XLR 135 XLR 138 XLR 139 XLR 140 GTL 142 GTL 158 GTL 1000 GTL 2000 GTL	555555555555555555555555555555555555555	TC5080P TC5080P 858 858 8719 8719 8719 2816 8734	UFO-T UFO-T RDS-1, UFO RDS-1, UFO RDS-6, UFO RDS-6, UFO RDS-5, UFO N/A RDS-5, UFO

MODEL	TYPE	PLL CHIP USED	DIGI-SCAN REQUIRED
COURIER			
Caravelle 40-D Conquerer 40-D Gladiator Spartan Centourian	A S S S	5104 SM5104 858 858 858	N/A N/A 10 RDS-1, UFO10 RDS-1, UFO10 RDS-1, UFO
FANNON			
Fanfare 350-F	s	858	RDS-1, UFO
HY GAIN			
623, 623A	S	Descrete	UFO ³
MIDLAND			
78-976 78-999 79-893 79-892 79-900 76-863 78-892	S S S S A S	PLL-02 PLL-02 858 PLL-02 8719 PLL-02 PLL-02	RDS-02, UFO RDS-02, UFO RDS-1, UFO RDS-02, UFO RDS-6, UFO N/A 2 xtals RDS-02, UFO
BOWMAN			
CB-950	S	PLL-02	RDS-02, UFO
PALOMAR			
SSB-500 SSB-500 4100	S S A	145106 7120 02A	UFO ⁴ UFO N/A 2 xtals
TEABERRY			1
T Command Stalker 101 Stalker 102 Stalker 1 & 2	. A S S S	858 858 858 Descrete	UFO, RDS-1 RDS-1, UFO RDS-1, UFO UFO
REALISTIC			
TRC-449 TRC-455 TRC-458 TRC-457 TRC-57	8888	858 858 858 858 Descrete	RDS-1, UFO RDS-1, UFO RDS-1, UFO RDS-1, UFO UFO
ROBYN			
SB-505 SB-510D	S S	8719 858	11,1125, RDS-6, UFO RDS-1, UFO

MODEL	TYPE	PLL CHIP USED	DIGI-SCAN REQUIRED
ROBYN SB-505 SB-510D SB-520D	S S S	8719 858 858	11,1125, RDS-6, UFO RDS-1, UFO RDS-1, UFO
SEARS 663.38060600 934.38110700 934.38270700 934.28360700	A S S S	858 SM5104 SM5104 SM5104	RDS ₅ 1, UFO ¹ 5 UFO UFO UFO
RCA 14T-303	A	PLL-02	N/A 2 xtal
NDI PC200 Johnson 9740	s s	NDC-40013 NDC-40013	uro ⁶ uro ⁶
COLT 1200 390 485	s s	PLL-02 PLL-02 PLL-02	RDS-02, UFO N/A 2 xtal RDS-02
GEMTRONICS 6TX-77	S	PLL-02	RDS-02, UFO
JC PENNEY 981-6247 981-6241	s s	02A SM5104	RDS-02, UFO UFO
PACE 1000NC	s	40013	UFO
LAFAYETTE SSB-140	S	PLL-02	RDS-02, UFO
TRAM D-62 D-80 D-64 D-300	S S S	5080 8719 NDC40013 8719	UFO-T RDS ₆ 5, UFO UFO RDS-5, UFO
BROWNING Baron Mark IV	S A	TC5080P 145106	UFO ₇ T UFO
SBE 27CB 39CB 40CB	8 8 8	Descrete Descrete Descrete	UFO9 UFO9 UFO
SCOTT Dak 10	S	PLL-02	RDS-U2, UFO

REDCO UFO APPLICATIONS

TYPICAL PROBLEMS ENCOUNTERED WITH 8719 & 8734 SYNTHESIZERS:

- 1. DOWN MIXER OUTPUT SIGNAL (TP-10)
 - The Uniden 8719 & 8734 chassis have been found to have a relatively large difference in the amplitude of the down mixer signal available on TP-10. The UFO picks up this signal on Coax #1, amplifies the signal and compares it with an internal reference. Problems are encountered when the UFO does not get enough drive from the radio. This can cause an "out of lock" condition, and in this state the radio would be on some random frequency dependent only upon the FCO adjustment and not the UFO. To determine if an "out of lock" condition is caused by lack of drive, follow the procedure outlined on TA-002. A minimum of 3v peak to peak signal is required on Pin 2 for proper UFO operation. If the "out of lock" condition is caused by low drive, it can be cured by one of the following methods:

 RADIO MODIFICATION
 - a. Install a resistor from the base of TR-20 or Pin 10 of VCO chip to ground. This will improve the radio's gain by approximately 30%.

UFO MODIFICATION

b. Short the capacitor (.01uf) connecting the amplifier to Pin 2 of the PLL chip. Remove the 4.7k resistor to the right of the .01uf cap previously mentioned and replace with a 68k resistor.

Modification b. has been put into production of all new UFO's being manufactured as of 5-5-79.

2. VCO ADJUSTMENT

For maximum range and a clean sounding radio it is highly recommended the VCO be aligned in the following manner: (Note: Us a non-metallic alignment tool)


- a. Set UFO to 28,000 MHz.
- b. Turn the VCO adjustment to a point where the radio is near 27.950.
- c. Align the VCO slug very slowly until the VCO just locks at 28,000 and do not turn the VCO past this point.

Other alignment procedures may cause loop filtering adjustments to be very critical and the radio may not be clean over a wide range of frequencies.

3. LOOP FILTERING

The addition of a variable loop filter on 8719 & 8734 radios is occasionally a necessity. A variable loop filter allows the technician to vary the loop filtering and make up for variables present in synthesizer circuits of radios. Symptoms of the loop filtering being incorrect may be: distorted SSB, warble on SSB, difficult to clarify SSB, or, in extreme cases, squeal on AM and bleedover may be present. In most cases the problems described above are most easily cured by the addition of a variable loop filter consiting of a variable resistor (usually a trimpot) in series with an electrolytic capacitor. Values of 10uf & 10k have been used here at the factory quite successfully. This loop filter is added between TP9 and ground.

Better results can be achieved by removing the capacitors inside the UFO which normally compose the loop filters. These capacitors are identified in the programming section of the instruction manual as they are removed for 858 installations. The loop filter is aligned for best SSB clarity, If the resistance of the trimpot is too low, the radio will warble on higher frequencies; and, if the resistance is too high bleedover may be experienced on lower frequencies.



REDCO DIGI-SCAN 6


UFO INSTALLATION TO BROWNING MARK IV A

- 1. Do not remove 145106 PLL chip.
- 2. Connect the center of Coax 1 to the Junction of R-708 and R-709.
- 3. Remove R-715 and C-734.
- 4. Connect the center of Coax 2 to TP-3.
- 5. Install a 10uf cap and 10k pot in series from TP-3 to ground.
- 6. Remove loop filtering capacitors in UFO as in 858 installation.
- 7. Cut the foil trace connecting to Pin 8 of the 145106 chip.
- 8. Connect the foil trace that was connected to Pin 8 to an 8v source.

PROGRAM CODE: B B W W B B B B W W

UFO INSTALLATION TO REALISTIC TRC 57

- 1. Hook center of Coax 1 to TP-4 (Junction R321 and R322),
- 2. Remove the 10k resistor connecting to TP3.
- 3. Hook center of Coax 2 to TP3.
- 4. Add a 10uf electrolytic cap and a 10k pot in series from TP3 to ground.



- 5. Align VCO for maximum range (L11)
- 6. Remove final RF amp.

PROGRAM CODE: W B B B W W B W B B B B W W

UFO INSTALLATION TO

HY-GAIN 623-A

- 1. Remove VCO shield (L-603).
- 2. Replace 330pf cap (C634) with 100 pf.
- 3. Remove R-308.
- 4. Hook center of Coax 2 to the side of R-308 that goes to the connector (VCO control).
- 5. Hook center Coax 1 to Pin 1 of IC 301.
- 6. Install a 10uf electrolytic cap and a 10k pot in series from the center of Coax 2 to ground.
- 7. Remove V-501.

PROGRAM CODE; BBBW WBWB BBBB WW

UFO INSTALLATION TO

NDI-PC200

APPLICATIONS: Chassis using 40013 synthesizer Chip examples: Tram D64, Pace 1000B, and Johnson 4740.

INSTALLATION:

- 1. Connect the center of Coax 1 to Pin 2 of the 40013 PLL chip.
- 2. Remove R-03 (1k).
- 3. Connect center of Coax 2 to the Junction R-02 and R-04.
- 4. Change 10.000 crystal Y1 to 10.240 MHz.
- 5. Remove CR-03.
- 6. Apply power and adjust L-5 for correct AM frequency.
- 7. Adjust L-6 for correct LSB frequency.
- 8. Remove Q705.

PROGRAM CODE: B B B B W B W W B B B B B B NOTE: Part designations above refer to NDI-PC200.


Part designations for Tram D64 are as follow: R-03 - R-903, R-02 - R-902, R-04 - R-904, CR-03 - CR-903,

PROGRAM CODE: D-64 B B W B B B W B W W W WW

NOTE: USB will be 5 kc below the frequency display.

TROUBLESHOOTING AN OUT OF LOCK CONDITION

The following flow chart describes troubleshooting an out of lock condition. Align the VCO for an operating frequency about 200 KHz above the UFO setting. Program UFO correctly.



As the VCO is adjusted through the frequency displayed by the UFO, the voltage on Coax #2 should change its logic state.

OUT OF LOCK: In an "out of lock" condition varying the UFO frequency setting will not change the radio frequency. A voltage measurement on the TP-2 will quickly determine a locked or unlocked condition. Ov for locked. 5v for unlocked.

LIMITED RANGE: An "out of lock" condition at the top or bottom end of the band.

WARBLE: A warble is detected on SSB. This can cause SSB comnunications to be distorted or difficult to clarify.

RADIO OFF FREQUENCY BY A MUTIPLE OF 5KHz: Radio in lock but the operating frequency is constantly off by some multiple of 5KHz.

RECEIVES 2 OR MORE CHANNELS AT ONCE: When receiving, the same incoming signal can be heard on several frequencies.

WILL NOT LOCK WHEN POWER IS RESET: A radio may function normally after re-alignment, but, when the power is turned off and then turned on again, it may not relock. The reason this condition can exist is as follows: Power is first applied and the UFO circuitry has no input on Coax 1 because the VCO has not begun to oscillate. The UFO senses the lack of input and puts out a high (5v) state on Coax #2. The VCO then oscillates at its maximum frequency, and because of inherent design its amplitude decreases at higher frequencies; therefore, the down mixer output is low and the UFO cannot get enough drive from the radio on Coax #1. The PLL chip does not get enough drive and the loop is unable to recover. The problem is solved by increasing the gain of the down mixer or input amplifier or re-adjusting the VCO coil to a point where the VCO will not run as high in frequency. Use the VCO alignment suggested later in this text.


LOOP FILTERING: The addition of a variable loop filter on radios is occasionally a necessity. A variable loop filter allows the technician to vary the loop filtering and make up for variables present in synthesizer circuits of radios.

Symptoms of the loop filtering being incorrect may be: distorted SSB, warble on SSB, fifficult to clarify SSB, or, in extreme cases, squeal on AM and bleedover may be present. In most cases the problems described above are most easily cured by the addition of a variable loop filter consisting of a variable resistor (usually a trimpot) in series with an electrolytic capacitor. Values of louf and lok have been used here at the factory quite successfully. This loop filter is added between the center of Coax #2 and ground.

Better results can be achieved by removing the capacitors inside the UFO which normally compose the loop filter. These capacitors are identified in the programming section of the instruction manual as they are removed for 858 installations. The loop filter is aligned for best SSB clarity. If the resistance of the trimpot is too low, the radio will warble on higher frequencies; and. if the resistance is too high, bleedover may be experienced on lower frequencies.

GROUND CONNECTIONS: For proper operation the UFO must have a good ground loop to the radio. Best results are achieved by connecting the shields near the VCO and connecting the black wire to a ground near the voltage regulator.

BROKEN PC PADS: The pads under the PLL chip are sometimes damaged during chip removal. The 8v source is connected through one of the pads and the circuit must be complete through the pad to attain a locked condition on 8719 installations.





REDCO MODEL MARK IV

The REDCO MARK IV RF Monitor is a high quality instrument for measuring Standing Wave Ratio (SWR), Transmitted power and percent modulation.

REDCO'S MARK IV is designed by Redco/Conductron for CB and Ham radio applications. Power scales are factory calibrated at 26MHz, (if desired the three power scales can be individually calibrated for any frequencies between 1Mhz and 250Mhz.).

The SWR and Modulation functions are broad-band and will operate from 1Mhz to 250Mhz.

THE MARK IV FEATURES:

RF power scales of 0-10, 0-100, 0-1000 watts, 5% accuracy

SWR scale displays SWR and percent reflected power.

Modulation displayed in % and decibels (-21db to +3db)

Precision 6-inch D'Arsonval multiscale meter, 5ua, 2% accuracy

Directional forward power/reflected power discrimination= 30db (i.e. 1000 times)

Completely passive, requires no external power source

Inline operation. Will not disturb the tuning of your antenna system. Draws negligible power.

Uses standard UHF coaxial connectors.

REDCO'S Digi-Scan systems are manufactured as receiving systems only, and to use them for transmission in the United States is in direct violation of the Federal Communications Commission.

REDCO MODEL MARK V

REDCO'S MARK V wattmeter is a 3 meter system to allow continuous monitoring of RF Power, SWR and modulation.

For accuracy and reliability a calibrated dial on the front panel can be set to any frequency from 3 Mhz to 250 Mhz. A frequency selector switch is provided to allow you to set your dial on any frequency you would like to operate within the spectrum frequencies of 50, 100, 150, 200, and 250Mhz. A special channel provided for CB operating frequencies.

Only REDCO/CONDUCTRON could design and manufacture such a tech-nological breakthrough in the wattmeter field.

FEATURES:

- 1-The ultimate broad band from 3Mhz to 250Mhz, AM, CW, SSB operations
- 2-A passive system, no external power required
- 3-Unique solid state design provides negligible insertion loss 100%. Modulation readout extends from -20db to +3db. Modulation is a function of voice level. (This level can be adjusted to read 100% for best communication transmission).
- 4-Standing Wave Ratio readout is indicated on the SWR meter by means of a unique design balanced breech circuit, termination 50 Ohms (forward and reflected power ratio).
- 5-MARK V is simple to connect to your transceiver system by 2 coaxial connectors, and is inserted between the antenna and transmitter.

SPECIFICATIONS: