



MODIFICATIONS

EAGLE - Model 200

DRIVER MODIFICATION:




Factory Issue



After Modification

OUTPUT MODIFICATION:



Factory Issue as depicted above. To modify, remove capacitors (1KV120 & 30N150) across "Load" and "Drive" Controls. Cut as indicated by "X's".