

CORRECTIONS


Volume 25, page 6: CHANGE.....headings on alignment procedure,
Receiver to Transmitter,
Transmitter to Receiver.....

Volume 21, page 14: CHANGE.... 6. Remove D31, not D32.....

Volume 19, page 34: CHANGE.... GRANT-DX, 10KHz JUMP MOD; title to now read
GRANT-DX, "MISSING Fo's MOD".

Volume 25, page 19: We have been informed that instead of R106, it should
read D22 is the AMC disable if needed.

Volume 25, page 28: Galaxy 2100 - Step #7 should read: Remove ORANGE wire
completely and solder ORANGE wire where WHITE wire was,
other end to hole left open at JP9.



PLEASE BE ADVISED THAT THE VOICE SIGNAL BOOSTER "VSB-1", SECRET CB KIT #102,
WILL NOT WORK IN THE TRAM RADIOS. DISREGARD THE INFORMATION IN VOLUME 10,
PAGE 18 and VOLUME 12, PAGE 66.

Are you interested in ANTIQUE RADIOS? If you are, try this address for more
information. A.R.C., 9511-23 Sunrise Blvd., Cleveland, OHio 44133