



EQUIPMENT AFFECTED

Messenger 250
Part No. 242-0250-001

REASON FOR REVISION

Improve tone quality from the speaker.

REVISION

1. Replace C16 with a 0.01 μ F capacitor.
2. Remove R35.

PARTS REQUIRED

<u>QTY</u>	<u>PART NUMBER</u>	<u>PART DESCRIPTION</u>
1	510-1003-103	Capacitor C16, 0.01 μ F \pm 10%, 250V

CHANGE ACTION

Make this change as required, this change has been included in the "B" model transceiver.