

ENGINEERING CHANGE NOTICE

| | | |
|---|-------------------|----------------------|
| PROBLEM DESCRIPTION (be specific) | Date: | April 3, 2009 |
| Low power out of transmitter at band edges, and different operating modes | ECN No. | G030409 |
| | Requested by: | |
| | Engr Approval: | Magnum Int'l |
| | RF Ltd Approval | SIL |
| | Service Approval | |
| | Mfg Approval | |
| | Field Retrofit? | Yes |
| | MOD LEVEL CHANGE? | |

| APPLICABILITY | S3-50 | S6-50 | S9-50 | S3-80 | S6-80 | S9-80 | OTHER |
|---|-------|-------|-------|-------|-------|-------|-------|
| List Serial Numbers Affected (if known) | | | | | | | |
| 0619 R4 boards only | Y | Y | Y | Y | Y | Y | |
| All S-Series Radios using 0619 Main Boards | | | | | | | |

| SOLUTION |
|---|
| R407 was: 470 Ohm R407 is: 220 Ohm Replace R407 with new value. |