



Hallmark Transceiver Tester

NOTES:

1. All capacitors are in pf and all resistors are $\frac{1}{2}$ w \pm 10% unless otherwise specified.
2. If L2 does not tune satisfactorily on all xtals installed, remove slug from coil.
3. C12 exists as distributed capacity in L2 osc. coil.