


COBRA 135-B
15KC SLIDER



- (1) Remove the unit from its cabinet and locate the crystal board and remove the screws holding it.
- (2) Carefully turn the unit over and solder a small piece of wire across the points shown.
- (3) Re-mount the crystal board back in its place and adjust the three controls on the top of the board as shown.

NOTE: There are many versions of the 135 crystal board due to various design changes. The one shown here is the most common and the others can be changed in the same manner.

