


SUPER CLARIFIER  
HELPFUL HINTS

- (1) Note that parallel capacitors are pulled out when installing super diodes. (See locations A, B, and C).
- (2) When installing super diodes, be careful to observe polarity. Use isolated tip soldering iron only!



Location of varactor in typical 858 chassis. Note that there are three diodes. All three diodes must be replaced when desiring slide in AM, USB, and LSB. Use super clarifier diodes to improve clarifier range up to 300%.