

OPPS, WE GOOFED! cont'd.


VOL. 10, PAGE 48 : Step 5 should read - Clip D205.

VOL. 11, PAGE 4 : 3rd line from bottom should read -
29.805 on channel 40.

VOL. 11, PAGE 6 : For logic 26.645, Pin 14 is 0.

VOL. 11, PAGE 10 : 11.5816 should read 11.5858. *Even the corrected Pg is Fuck up 68 instead of 58*

VOL. 11, PAGE 41 : Diagram Correction:



VOL. 11, PAGE 75 : Replace 03A with 02A (rewiring necessary) for extra channels.

