

CORRECTIONS

SCB Vol. 15, pg 48: Royce 1-639, Pace 8093 (CCI-3001)  
"Slider" #6.....**CHANGE**, 'the middle'  
to read - unused.

---


SCB Vol. 21, pg 35: Reference to TRC-86/208/214....  
\* \* See page 48 for Fo Mod. Notes.  
Change to read page 20.

---

Excalibur SSB: Owner's Manual line-up procedure....  
Step 5. G, 2: correct the frequency to  
read 26.495MHz.

---

SCB Vol. 21, pg 18: 10KHz Jump Mod. Add....  
ADD.... solder 4.3K  $\frac{1}{4}$ W 5% resistor from  
pin 8 to pin 9 of IC-6. OR add at the  
switch modification as shown below.



SCB Vol. 12, pg 40: RE: Specific Tune-up on President AR-7.  
"Remove TR17, AMC Limiter"- **WRONG...**  
**CHANGE TO READ: Remove D8, AMC Limiter.**

---

