



Consumer Response Group

6500 W. Cortland Street * Chicago, IL 60707 * Phone: 773-889-8870 * FAX: 773-622-2269

September 16, 2004

Page 1 of 2

TECHNICAL SERVICE BULLETIN 10037

MODEL(S): All 25s with front microphone connector

DESCRIPTION: Excessive alternator whine.

ACTION: Remove C170. See the picture on page 2.

ADJUSTMENTS: None.

NOTES: None.

